



Model Year (MY)	Engine	Model(s)	Note	Previous P/Ns	ADAPT Drive with spring P/N	0-3000/0-5000				3,000-6,000				5,000-9,000				MY 2016 6,000-9,000				MY 2017-2021 6,000-8,000				MY 17-21 8,000-10,000				9,000+/ Mountain 10,000+			
						Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm		Drive Spring (included with ADAPT Clutch)		Cam Arm	
						P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile	P/N	LBS	P/N	Profile
2017-2021	9000	ZR, XF	*	0746-875, 0746-889, 0746-898	0746-934	1646-015	105/225	1646-116	S2-66	1646-015	105/225	1646-116	S2-66	1646-015	105/225	1646-116	S2-66	1646-015	105/225	1646-116	S2-66	1646-015	105/225	1646-116	S2-66	1646-015	105/225	1646-116	S2-66				
2016	9000	ZR, XF, M	+																														
2018-2021	8000	ZR	**	0746-888, 0746-885, 0746-895	0746-933	1646-009	85/225	1646-116	S2-66					1646-009	85/225	1646-113	S2-60									1646-009	85/225	1646-111	S2-56				
2018-2021	8000	M	**	0746-888, 0746-885, 0746-895	0746-933	1646-009	85/225	1646-116	S2-66	1646-009	85/225	1646-115	S2-64					1646-009	85/225	1646-114	S2-62	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58				
2019-2021	8000	Norseman	**	0746-888, 0746-885, 0746-895	0746-933	1646-009	85/225	1646-116	S2-66					1646-009	85/225	1646-114	S2-62									1646-009	85/225	1646-112	S2-58				
2019-2021	8000	Riot	**	0746-888, 0746-885, 0746-895	0746-933	1646-009	85/225	1646-116	S2-66					1646-009	85/225	1646-113	S2-60									1646-009	85/225	1646-111	S2-56				
2018-2019	8000	XF High Country	**	0746-888, 0746-885, 0746-895	0746-933	1646-009	85/225	1646-116	S2-66	1646-009	85/225	1646-115	S2-64	1646-009	85/225	1646-114	S2-62	1646-009	85/225	1646-114	S2-62	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58				
2016-2017	8000	ZR	***	0746-881, 0746-862	0746-933	1646-009	85/225	1646-116	S2-66					1646-009	85/225	1646-113	S2-60									1646-009	85/225	1646-111	S2-56				
2016-2017	8000	M	***	0746-869, 0746-881, 0746-862	0746-933	1646-009	85/225	1646-116	S2-66	1646-009	85/225	1646-115	S2-64					1646-009	85/225	1646-114	S2-62	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58				
2016-2017	8000	XF High Country	***	0746-869, 0746-881, 0746-862	0746-933	1646-009	85/225	1646-116	S2-66	1646-009	85/225	1646-115	S2-64					1646-009	85/225	1646-114	S2-62	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58				
2016	8000	XF	***	0746-862	0746-933	1646-009	85/225	1646-116	S2-66					1646-009	85/225	1646-113	S2-60									1646-009	85/225	1646-111	S2-56				
2018-2019	7000	ZR	*	0746-887	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-108	S2-50				
2016-2019	7000	Bearcat XT, Pantera XT	TBD		N/A	TBD	TBD	TBD	TBD					TBD	TBD	TBD	TBD									TBD	TBD	TBD	TBD				
2018-2019	7000	Pantera	*	0746-887	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-108	S2-50				
2018	7000	XF	*	0725-887	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-108	S2-50				
2016-2017	7000	ZR	*	0746-852,	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-109	S2-50				
2016-2017	7000	XF	*	0746-852	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-108	S2-50				
2016	7000	M	*	0746-852	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-109	S2-50				
2016	7000	XF High Country	*	0746-852	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-108	S2-50				
2016-2017	7000	Pantera	*	0746-852	0746-947	1646-159	45/225	1646-111	S2-56					1646-159	45/225	1646-109	S2-52									1646-159	45/225	1646-109	S2-50				
2018-2021	6000	ZR	**	0746-885, 0746-895	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2018-2021	6000	M	**	0746-885, 0746-895	0746-933	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58					1646-009	85/225	1646-111	S2-56	1646-009	85/225	1646-110	S2-54	1646-009	85/225	1646-109	S2-52				
2020-2021	6000	Riot	**	0746-885, 0746-895	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2018-2019	6000	Norseman	**	0746-885	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2018-2019	6000	Pantera	**	0746-885	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2018-2019	6000	XF High Country	**	0746-885	0746-933	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58					1646-009	85/225	1646-111	S2-56	1646-009	85/225	1646-110	S2-54	1646-009	85/225	1646-109	S2-52				
2018	6000	XF	**	0746-885	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2016-2017	6000	ZR	****	0746-881, 0746-862	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2016-2017	6000	M	****	0746-881, 0746-862	0746-933	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58					1646-009	85/225	1646-111	S2-56	1646-009	85/225	1646-110	S2-54	1646-009	85/225	1646-109	S2-52				
2016-2017	6000	XF High Country	****	0746-869, 0746-881, 0746-862	0746-933	1646-009	85/225	1646-113	S2-60	1646-009	85/225	1646-112	S2-58					1646-009	85/225	1646-111	S2-56	1646-009	85/225	1646-110	S2-54	1646-009	85/225	1646-109	S2-52				
2016	6000	XF	****	0746-881, 0746-862	0746-933	1646-009	85/225	1646-113	S2-60					1646-009	85/225	1646-111	S2-56									1646-009	85/225	1646-109	S2-52				
2016-2017	5000	ZR	+																														

It is recommended to install a new drive belt when installing a new drive clutch. Premature belt failure could occur if a new drive belt is not installed when replacing the drive clutch.

8639-454 hardware kit is needed for: cam arms, ring gear and/or dampener

Use 2015 Drive clutch & calibration

Use Adapt Drive clutch w/spacer (2623-326), remove washer, & use 0627-112 drive belt

Use Adapt Drive clutch w/spacer (2623-325), & remove washer

Use Adapt Drive clutch w/spacer (2623-325), remove washer, Remove adjuster in driven, & use 0627-111 drive belt

Use Adapt Drive clutch w/spacer (2623-325), remove washer, Remove adjuster in driven, & use 0627-107 drive belt

+

\*

\*\*

\*\*\*

\*\*\*\*